

-6-

22 June 1963
p. 10

⌘ - PNS
∅ - Anderson
∅ - Nugent

BM	9.65	7712.79		7703.14	top of E ₁ S.19. As return run on p. 9 did not check satisfactorily I rerun line. Evidently rodman did not have rod securely set.
t15	14.75	7722.18	5.36	7707.43	
t16	8.90	7728.76	2.32	7719.86	
t17	5.13	7726.55	7.34	7721.42	
t18	13.91	7733.80	6.66	7719.89	
t14			9.82	7723.98	
TBM N	8.25	7705.75		7697.50	See p. 7
t50	2.24	7698.85	9.14	7696.61	
			8.80	7690.05	ditch bottom at fence Willow Lake Ditch
			9.23	7689.62	upstream 25'
			7.30±	7691.55	upstream 50'
			9.50±	7689.35	downstream 25'
t50	9.27	7705.88	2.24	7696.61	
TBM N			8.37	7697.51	

Paul N. Scherbel
Paul N. Scherbel

Subscribed in my presence and sworn to before me this 10th day of July, 1963.



Mrs. Rachel A. Scherbel
Notary Public

My commission expires 5 December 1965.